






ANEXO 14 (c)
RELATÓRIO FOTOGRÁFICO ELABORADO
PELA EQUIPE DE FISCALIZAÇÃO DA SECID
ACERCA DAS INCONFORMIDADES
CONSTATADAS NA EXECUÇÃO DO
CONTRATO Nº 060/2012/SECOPA
(PARTE 2)

INCONFORMIDADES CONTRATO 060 / 2012

AV. SÃO SEBASTIÃO

TRECHO:







ITEM	ACHADO	FOTOGRAFIA
20	Trincas Longitudinais	
21	Trampa de boca de lobo quebrada	
22	Trincas Longitudinais	

INCONFORMIDADES CONTRATO 060 / 2012

AV. SÃO SEBASTIÃO

TRECHO:






ITEM	ACHADO	FOTOGRAFIA
23	Meio Fio danificado e inexecução de sargeta	 A photograph showing a close-up of a concrete curb and gutter. The curb is cracked and uneven, and the gutter is filled with dirt and debris, indicating damage and poor maintenance.
24	Trincas Longitudinais	 A photograph showing a close-up of asphalt pavement. Several long, parallel cracks are visible, running across the width of the road, indicating structural damage.
25	Tampa de boca de lobo quebrada	 A photograph showing a broken concrete manhole cover. The cover is cracked and displaced, with debris and vegetation around it, indicating a safety hazard.

INCONFORMIDADES CONTRATO 060 / 2012

AV. SÃO SEBASTIÃO

TRECHO:







ITEM	ACHADO	FOTOGRAFIA
26	Trincas Longitudinais e Transversais	
27	Trincas Longitudinais e Transversais	
28	Trincas Longitudinais e Transversais	

INCONFORMIDADES CONTRATO 060 / 2012

AV. SÃO SEBASTIÃO

TRECHO:



ITEM	ACHADO	FOTOGRAFIA
29	Trincas Transversais	 A photograph of a paved road surface showing several transverse cracks. The road is flanked by buildings and parked cars.
30	Trincas Longitudinais	 A close-up photograph of a paved road surface showing several longitudinal cracks.
31	Trincas Longitudinais	 Another close-up photograph of a paved road surface showing several longitudinal cracks.

INCONFORMIDADES CONTRATO 060 / 2012

AV. SÃO SEBASTIÃO


TRECHO:






ITEM	ACHADO	FOTOGRAFIA
32	Trincas Transversais	

INCONFORMIDADES CONTRATO 060 / 2012
RUA TRAÇAIA

TRECHO:



ITEM	ACHADO	FOTOGRAFIA
1	Panelas	
2	Panelas	
3	Panelas	

4	Panelas	 A close-up photograph of a pothole in asphalt pavement. The pothole is roughly circular and contains a mound of brownish soil or sand. The surrounding asphalt is cracked and shows signs of wear.
5	Panelas	 An aerial photograph of a pothole in asphalt pavement. The pothole is roughly circular and contains a mound of brownish soil or sand. The surrounding asphalt is cracked and shows signs of wear.
6	Panelas	 A wide-angle photograph of a pothole in asphalt pavement. The pothole is roughly circular and contains a mound of brownish soil or sand. The surrounding asphalt is cracked and shows signs of wear. In the background, a white car is parked on the street, and a person is walking. The shadow of the person taking the photo is visible in the foreground.